

2	1	
PART NAME	QTY.	
P SHADE SUB ASSEMBLY	1	
P ARMS	4	
W PLATE	2	D
T PLATE	2	
R BASE PLATE	1	
ER BASE PLATE	1	
OCK	3	
GE LOCK	6	
FEET	3	
COLLAR PLATES	1	
NECK	1	
INING PLATE	1	
JLDER PLATE	2	С
ER WEDGE	2	

# 1 3/8"D X 3/4" THK. PUCKS ARE OMITTED FROM THIS EXPLODED VIEW. 18 REQUIRED


В

А

## John Induna AD DATE 01/06/2012 DRAWN BY JA TITLE: FILE NAME JA-Lamp- Instructables SIZE REV В

•	¢	כ
	C	2


1




В


А


8





7





4

5

6

3


### PROPRIETARY AND COI

THE INFORMATION CONTA DRAWING IS THE SOLE PRO JOHN ALLEN. ANY REPRO OR AS A WHOLE WITHOUT PERMISSION OF JOHN ALLE

do not scale dr

SCALE: 1

3



DIMENSIONS ON THESE DRAWING ALLOW FOR ZERO CLEARANCE. MAKE ALLOWANCE AS YOU SEE FIT.

## John Induna AD

ONFIDENTIAL	DATE (	TE 01/06/2012 DRAWI			NBY JA		
AINED IN THIS OPERTY OF DUCTION IN PART I THE WRITTEN .EN IS PROHIBITED.	TITLE:						
RAWING	size <b>B</b>	FILE NAME JA-Lamp-	-	ctables		REV	
:6					SHEE	T 3 OF 8	
	2				1		

В

